




# Motorola W490 LCD Screen Replacement

This guide is an instruction on how to locate and remove the LCD screen.

Written By: Will Edwards






## TOOLS:


- [T5 Torx Screwdriver](#) (1)
  - [iFixit Opening Tools](#) (1)
-

## Step 1 — Upper Metal Frame



- Use the blue plastic opening tool to pry off all four of the rubber stickers from the upper inside face.
- Use the Torx T5 screwdriver to remove the four 5.4 mm screws from the upper inner face.



## Step 2



- Use a flathead screwdriver or plastic opening tools to help pry the top cover away from the phone.





### Step 3



- Pull the flex cable connection away from the top of the phone.

### Step 4




- Pull the camera connection away from the top of the phone.

## Step 5



- Pull the upper metal frame away from the phone.

## Step 6 — LCD Screen



- Hold the outer phone casing and pull the LCD screen out.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-07 11:20:17 AM.